




# Replaces Toro Groundsmaster 4000-D

## Parts

Rotary Mower - Model 30605

Impact Arm



All original equipment manufacturers names and part numbers are used for identification purposes only, and we are in no way implying that our products are original equipment parts. Prices subject to change without notice.



# Replaces Toro Groundsmaster 4000-D Parts

Rotary Mower - Model 30605  
Impact Arm



| Item No | R&R Part No. | OEM Part No. | Description | Qty Req | Order Quantity |
|---------|--------------|--------------|-------------|---------|----------------|
|---------|--------------|--------------|-------------|---------|----------------|

## Other Parts Available

|    |                     |                                                                                                                                                |                                 |   |  |
|----|---------------------|------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------|---|--|
| 70 | <b>R120-8883</b>    | 120-8883                                                                                                                                       | Arm Assy - RH Rear              | 1 |  |
| 71 | <b>R256-113</b>     | 256-113                                                                                                                                        | Bushing - 3/4 ID x 1 1/8 Flange | 4 |  |
| 72 | <b>R302-5</b>       | 21-6010,<br>302-11,<br>302-37,<br>302-47,<br>302-5,<br>302-57,<br>302-58,<br>302-6,<br>31-0300,<br>32-9660,<br>60-0800,<br>62-3880,<br>92-4181 | Fitting - Grease                | 2 |  |
| 73 | <b>R120-8884</b>    | 120-8884                                                                                                                                       | Arm Assy - LH Rear              | 1 |  |
| 74 | <b>R120-8856-03</b> | 120-8856-03                                                                                                                                    | Bracket- Roller - LH            | 1 |  |
| 75 | <b>R120-8874-03</b> | 120-8874-03                                                                                                                                    | Bracket- Roller - RH            | 1 |  |
| 76 | <b>R105-3249</b>    | 104-7512,<br>105-3249                                                                                                                          | Damper                          | 2 |  |
| 77 | <b>R104-7520</b>    | 104-7520                                                                                                                                       | Spring - Damper                 | 2 |  |
| 78 | <b>R105-2809</b>    | 105-2809                                                                                                                                       | Tube - Link                     | 2 |  |
| 79 | <b>R105-2808</b>    | 105-2808                                                                                                                                       | Rod End                         | 4 |  |
| 80 | <b>RMM607</b>       | 01-158-0610,<br>01-191-0820,<br>21-3900,<br>3220-5,<br>45-0170,<br>5/1/3220                                                                    | Nut - Jam 1/2-20 Zinc           | 4 |  |

All original equipment manufacturers names and part numbers are used for identification purposes only, and we are in no way implying that our products are original equipment parts. Prices subject to change without notice.



# Replaces Toro Groundsmaster 4000-D Parts

Rotary Mower - Model 30605  
Impact Arm



| Item No | R&R Part No.        | OEM Part No.                                                      | Description                    | Qty Req | Order Quantity |
|---------|---------------------|-------------------------------------------------------------------|--------------------------------|---------|----------------|
| 81      | <b>RF5003</b>       | 32127-29,<br>32131-5,<br>32132-5,<br>3296-23                      | Locknut - ESNA 1/2-13          | 6       |                |
| 82      | <b>R325-9</b>       | 01-150-0920,<br>01-178-0818,<br>18-9540,<br>3226-5                | Bolt - 1/2-13 x 2 1/4 Hex Head | 2       |                |
| 83      | <b>R322-10</b>      | 20-30-AD,<br>24-7180,<br>322-10,<br>322-10 ,<br>3223-6,<br>513347 | Bolt - Hex HD 5/16-18 x 2      | 4       |                |
| 84      | <b>R104-8331</b>    | 104-8331                                                          | Rod End - Spherical            | 4       |                |
| 85      | <b>R3296-29</b>     | 1-804256,<br>3290-357,<br>3296-29,<br>915662P                     | Locknut - 5/16-18 ESNA         | 4       |                |
| 86      | <b>R443118</b>      | 01-188-0813,<br>22-15-AJD,<br>3217-9                              | Nut - 1/2-13 Zinc              | 4       |                |
| 87      | <b>R105-4551</b>    | 105-4551                                                          | Washer- Flat                   | 4       |                |
| 88      | <b>R105-4552</b>    | 105-4552                                                          | Bearing - Plastic              | 2       |                |
| 89      | <b>R100-8138</b>    | 100-8138                                                          | Spring-Compression             | 2       |                |
| 90      | <b>R105-4548</b>    | 105-4548                                                          | Shaft - Spring                 | 2       |                |
| 91      | <b>R105-4550</b>    | 105-4550                                                          | Bushing - Straight             | 2       |                |
| 92      | <b>R105-2807-03</b> | 105-2807-03                                                       | Plate                          | 2       |                |

All original equipment manufacturers names and part numbers are used for identification purposes only, and we are in no way implying that our products are original equipment parts. Prices subject to change without notice.



# Replaces Toro Groundsmaster 4000-D Parts

Rotary Mower - Model 30605  
Impact Arm



| Item No | R&R Part No. | OEM Part No.                                                                                                              | Description                  | Qty Req | Order Quantity |
|---------|--------------|---------------------------------------------------------------------------------------------------------------------------|------------------------------|---------|----------------|
| 93      | R400264      | 01-150-0180,<br>01-178-0610,<br>20-48-AD,<br>20-48-AGD,<br>32-9160,<br>3224-3,<br>323-29,<br>323-7,<br>400264,<br>908035P | Bolt - Hex HD 3/8-16 x 1-1/4 | 8       |                |
| 94      | R3220-7      | 01-191-1216,<br>3220-7,<br>Mar-03                                                                                         | Nut - 3/4-16 Jam Zinc        | 2       |                |
| 95      | R105-2806    | 105-2806                                                                                                                  | Rod End                      | 2       |                |
| 96      | R3296-39     | 32127-25,<br>32128-36,<br>3290-357,<br>3296-17,<br>3296-22,<br>3296-39,<br>915663P,<br>99-7443                            | Locknut - 3/8-16 Nylon       | 8       |                |
| 97      | R3-6498      | 3--6498,<br>3-6498,<br>47-8270                                                                                            | Washer - Thrust              | 4       |                |
| 98      | R32120-93    | 32120-93                                                                                                                  | Snap Ring - HD               | 2       |                |
| 99      | R104-2281    | 104-2281                                                                                                                  | Shaft- Pivot                 | 2       |                |
| 100     | RF104        | 01-166-0020,<br>01-166-1010,<br>23-15-GD,<br>30-8480,<br>3253-8,<br>48-9400                                               | Washer - Lock 5/8            | 2       |                |
| 101     | R3296-53     | 3296-53                                                                                                                   | Locknut - 5/8-11 ESNA Yellow | 2       |                |
| 102     | R86-5350     | 86-5350                                                                                                                   | Bumper - Rubber              | 2       |                |

All original equipment manufacturers names and part numbers are used for identification purposes only, and we are in no way implying that our products are original equipment parts. Prices subject to change without notice.



# Replaces Toro Groundsmaster 4000-D Parts

Rotary Mower - Model 30605  
Impact Arm



| Item No | R&R Part No.        | OEM Part No.                                                                                        | Description                    | Qty Req | Order Quantity |
|---------|---------------------|-----------------------------------------------------------------------------------------------------|--------------------------------|---------|----------------|
| 103     | <b>R119-8308-03</b> | 119-8308,<br>119-8308-03                                                                            | Plate                          | 2       |                |
| 104     | <b>R3231-2</b>      | 01-157-0170,<br>01-173-0608,<br>3231-2,<br>3231-22,<br>3231-28,<br>900063P                          | Bolt - Carriage 3/8-16 x 1     | 4       |                |
| 105     | <b>R104-8301</b>    | 104-8301,<br>104-9301,<br>109-6658,<br>133-7570                                                     | Locknut - 3/8-16 Nylon Flanged | 4       |                |
| 106     | <b>R3296-2</b>      | 32127-10,<br>3296-2,<br>9157404                                                                     | Nut - #10 Lock                 | 4       |                |
| 107     | <b>R3290-360</b>    | 3290-360                                                                                            | Bolt                           | 4       |                |
| 108     | <b>R3256-26</b>     | 01-166-0540,<br>01-166-0820,<br>17-2530,<br>24-13-BD,<br>30-8570,<br>3256-26,<br>356206,<br>48-9390 | Washer - 1/2 in                | 10      |                |
| 109     | <b>R104-7521</b>    | 104-7521                                                                                            | Bushing                        | 4       |                |
| 110     | <b>R94-6604</b>     | 94-6604                                                                                             | Tube - Spacer                  | 1       |                |

All original equipment manufacturers names and part numbers are used for identification purposes only, and we are in no way implying that our products are original equipment parts. Prices subject to change without notice.