



62in & 72in Side & Rear Discharge Deck - Models 2814 60in Deck Parts







62in & 72in Side & Rear Discharge Deck - Models 2814 60in Deck Parts

| | R&R Part No. | OEM Part No. | Description | Qty Order Req Quantity |
|------|-----------------|----------------------|---|---|
| Rota | ry Blades | | | |
| 1 | RM128485 | M128485 | Mower Blade - Med Lift 21 in | 3 |
| Othe | r Parts Availa | ble | | |
| 42 | RTCU18744 | TCU18744, UC28193 | Wheel - 5 in x 2 3/4 | 2 |
| 43 | RAM125172 | AM125172 | Wheel Kit - Gage Wheel | 1 |
| 44 | RM141764 | M141764 | Eyebolt - Includes Flanged Locknut | 1 |
| 76 | RM163054 | M163054 | Grass Deflector - Upper | 3 |
| 77 | R253-133 | M85699 | Seal - Oil | 3 |
| 78 | RM88251 | M169375, M88251 | Bearing - Spindle | 6 |
| 79 | RM127198 | M127198 | Seal | 3 |
| 80 | R19M7489 | 19M7489 | Bolt Hex HD - M16 x 45 Gr 10.9 | 3 |
| 81 | RM115245 | M115245 | Roller | 4 |
| 82 | RM123522 | M123522 | Washer - Belleville - Blade Bolt | 3 |
| 83 | RM123520 | M123520 | Washer - Hardened | 3 |
| 84 | RTCU19299 | TCU19299 | Axle Bushing | 2 |
| 85 | R19M8006 | 19M8006 | Bolt - M8-1.25 x 120 Hx HD Fl Cl 10.9 | 2 |
| 86 | R14M7396 | 14M7396 | Locknut - Flanged Nyloc | 32 |
| 87 | RTCA17524 | TCA17524 | Idler Pulley - 5 in Flat Dia with .75 in Brg ID | 2 |
| 88 | RM141695 | M112398, M141695 | Idler - North America (Replaces M112398) | 1 |
| 89 | RAM129501 | AM129501 | Arm | 1 |
| | | | | |

All original equipment manufacturers names and part numbers are used for identification purposes only, and we are in no way implying that our products are original equipment parts. Prices subject to change without notice.





62in & 72in Side & Rear Discharge Deck - Models 2814 60in Deck Parts

| | R&R Part No. | OEM Part No. | Description | Qty Order Req Quantity |
|-----|-----------------|-----------------------|--|---|
| 90 | RM134382 | M134382 | Spindle - 25 mm w/M12-1.75 Blade Bolt Thrd | 3 |
| 91 | RM163053 | M134305, M163053 | Grass Deflector - Spindle | 3 |
| 92 | R24M7226 | 24M7226 | Washer - 13 x 35 x 5 mm | 1 |
| 93 | RTCU51223 | TCU51223 | Deflector - Grass | 3 |
| 94 | RM124203 | M124203 | Shaft | 2 |
| 95 | RM136044 | M136044 | Spring - Extension | 1 |
| 96 | RM133598 | M133598 | Shield | 2 |
| 97 | R14M7400 | 14M7400 | Locknut - 10mm | 3 |
| 98 | RTCA13570 | TCA13570 | Bracket | 1 |
| 99 | R24H1308 | 24H1308 | Washer | 1 |
| 100 | R14M7167 | 14M7167 | Nut - M10-1.5 Lock Nylon Insert | 1 |
| 101 | RM163058 | M127517, M163058 | Bushing - Sub For M127517 | 3 |
| 103 | R93-2559 | TCU23201 | Bearing | 2 |
| 104 | RM132309 | M132309 | Spacer | 2 |
| 105 | RM163060 | M133398, M163060 | Washer - Replaces RM133398 | 3 |
| 106 | R03M7184 | 03M7184 | Bolt - Carriage M8 | 4 |
| 107 | RTCU38142 | TCU14182, TCU38142 | Hub - Sub For TCU51119 or TCU14182 | 3 |
| 108 | RM123569 | M123569 | Flange Nut | 3 |
| 109 | RM127353 | M127353 | Bushing | 3 |
| 110 | R19M7868 | 19M7868 | Bolt - M8-1.25 x 30 HHF | 30 |
| | | | | |

All original equipment manufacturers names and part numbers are used for identification purposes only, and we are in no way implying that our products are original equipment parts. Prices subject to change without notice.





62in & 72in Side & Rear Discharge Deck - Models 2814 60in Deck Parts

| Item R&R No Part No. | OEM Part No. | Description | Qty Req | Order Quantity |
|--|-------------------|-------------------|------------|-------------------|
| 111 RR50647 | J16931, R50647 | Pin - Hair Cotter | 1 | |