




# Replaces Toro Greensmaster TriFlex

## 3320 Parts

*Dethatching Unit - Model 04720*  
*Groomer*



All original equipment manufacturers names and part numbers are used for identification purposes only, and we are in no way implying that our products are original equipment parts. Prices subject to change without notice.



# Replaces Toro Greensmaster TriFlex 3320 Parts

*Dethatching Unit - Model 04720  
Groomer*



| Item No | R&R Part No. | OEM Part No. | Description | Qty Req | Order Quantity |
|---------|--------------|--------------|-------------|---------|----------------|
|---------|--------------|--------------|-------------|---------|----------------|

## Blades

|   |                  |          |                                  |   |  |
|---|------------------|----------|----------------------------------|---|--|
| 1 | <b>R132-4626</b> | 132-4626 | Groomer Blade - Helix .035 Thick | 0 |  |
|---|------------------|----------|----------------------------------|---|--|

## Other Parts Available

|    |                  |          |                            |   |  |
|----|------------------|----------|----------------------------|---|--|
| 10 | <b>R125-3478</b> | 125-3478 | Groomer Shaft Assy         | 1 |  |
| 11 | <b>R115-6869</b> | 115-6869 | Bearing - Ball -Stainless  | 0 |  |
| 12 | <b>R115-6923</b> | 115-6923 | Shield - Bearing - Flocked | 2 |  |

All original equipment manufacturers names and part numbers are used for identification purposes only, and we are in no way implying that our products are original equipment parts. Prices subject to change without notice.