



Replaces Toro Workman 3300 Parts

Traction Unit

Steering & Controls



All original equipment manufacturers names and part numbers are used for identification purposes only, and we are in no way implying that our products are original equipment parts. Prices subject to change without notice.



Replaces Toro Workman 3300 Parts

Traction Unit
Steering & Controls



Item No	R&R Part No.	OEM Part No.	Description	Qty Req	Order Quantity
---------	--------------	--------------	-------------	---------	----------------

Filters

10	R108-3811	108-3811	Element - Air Cleaner	1	
10	R93-2195	93-2195	Baldwin Air Filter	1	
10	RRF10125	108-3808, 93-2195	SilverGuard Air Filter	1	
11	R106-2416	105-7968, 106-2416, 106-6732	Air Cleaner Assy	1	
12	R46-7510	46-7510	Hood-Inlet- Air	1	

Guages and Controls

30	R114-3315	114-3315	Solenoid -12 Vdc	1	
31	R94-4208	94-4208	Hourmeter	1	
32	R95-8999	95-8999	Switch - Headlight	1	
34	R151541	R&R ON, LY	Delta Seat Switch - Twist Mount 1 Pole Normally Open	1	
35	R106-6726	106-6726	Steering Pump Assy	1	
36	R27-2360	27-2360	Switch - Key 6 Lead 9/16 Mount	1	
37	R100-4918	100-4918	Diode	1	

Other Parts Available

70	RMXB180GY	106-6672, 112-2923, 119-8829, 133-0577	Milsco Seat XB180 - Grey	2	
----	------------------	---	--------------------------	---	--

*Detail Description: The Milsco XB180 bucket seat is designed with a sturdy vacuum formed waterproof vinyl cover that will not crack or peel. Ergonomic foam cushions ensure operator comfort. Features a durable blow molded plastic frame. Allows for an operator presence switch. Central drain hole prevents water build-up. 19 inch high-back seat will replace both original 16in and 19in high-back seats. Seat: 18.75in W x 18.8in H. Grey. Made in U.S.A.
Please note: Due to excessive air freight charges, this item will be shipped ground freight.:*

All original equipment manufacturers names and part numbers are used for identification purposes only, and we are in no way implying that our products are original equipment parts. Prices subject to change without notice.



Replaces Toro Workman 3300 Parts

Traction Unit

Steering & Controls



Item No	R&R Part No.	OEM Part No.	Description	Qty Req	Order Quantity
71	R98-1471	93-5212, 94-3500, 98-1471	Steering Wheel Assy - 14 in Incl Cap	1	
72	R98-1468	98-1468	Cap - 14" Steering Wheel	1	
73	R3234-29	3234-17, 3234-29	Bolt - 5/16-18x1 Serr Hex	10	
74	R87-9400	104-0498, 87-9400	Valve - Vacuator	1	
75	R93-2191	93-2191	Band-Mounting - Air Cleaner	1	
77	R150848	100-4928, 106-7848, 110-0413, 110-9720, 95-8910	Belt-Seat	2	
78	R2412-133	01-651-0160, 2412-133	Clamp	1	
79	R3234-11	3234-11	Bolt - Hex Washer HD	1	
80	R3212-4	3212-3, 3212-4, 3212-5	Bolt - Hex HD 7/16-20 x 1 GR5	2	
81	R99-7420	100-8493, 99-7420	Plug-Hole	3	
82	R150224	106-7847 & 107-7959, 107-7959, 119-0654 & 119-0655, 133-8896, 192-8990 & 92-8991, 92-8990, 92-8990/92-8991, 92-8991	Adjusters - Seat (Set of 2)	2	
83	R106-2475	106-2475	Brake Shaft Assy	1	
84	R63-3410	63-3410	Screw - Shoulder	2	


All original equipment manufacturers names and part numbers are used for identification purposes only, and we are in no way implying that our products are original equipment parts. Prices subject to change without notice.



Replaces Toro Workman 3300 Parts

Traction Unit

Steering & Controls



Item No	R&R Part No.	OEM Part No.	Description	Qty Req	Order Quantity
85	R256-156	256-156, 256-219	Bushing - Flanged	4	
86	R302-5	21-6010, 302-11, 302-37, 302-47, 302-5, 302-57, 302-58, 302-6, 31-0300, 32-9660, 60-0800, 62-3880, 92-4181	Fitting - Grease	2	
87	R66-3160	33114-020, 43-0110, 48-7710, 66-3160	Bolt - Flanged Hex HD	4	

All original equipment manufacturers names and part numbers are used for identification purposes only, and we are in no way implying that our products are original equipment parts. Prices subject to change without notice.