




Replaces Toro Greensmaster TriFlex

3320 Parts

DPA Cutting Unit - Models 04651, 04653 & 04655
Rear Roller Brush



All original equipment manufacturers names and part numbers are used for identification purposes only, and we are in no way implying that our products are original equipment parts. Prices subject to change without notice.



Replaces Toro Greensmaster TriFlex 3320 Parts

DPA Cutting Unit - Models 04651, 04653 & 04655
Rear Roller Brush



Item No	R&R Part No.	OEM Part No.	Description	Qty Req	Order Quantity
Belts					
20	R105-5720	105-5720	Belt - Poly V	1	
Other Parts Available					
70	R105-6792	104-1829, 105-6792	Brush - Rear Roller	1	
71	R251-259	251-259, 251-307	Bearing - Ball	1	
72	R104-4727	104-4727	Ring - Retaining	1	
73	R112-6957	112-6957	Washer - Hardened	2	
74	R301504	2296-42, 301504, 32127-24, 32128-33, 32146-17, 3296-16, 3296-42, 3296-42 , 915661P	Locknut - ESNA 1/4-20	2	
75	R115-7143	115-7143	Spring - Wave	2	
76	R104-8300	104-8300, 104-8300 , 119-4041	Locknut - 5/16-18 Flanged Y/Zinc	5	
77	R3234-29	3234-17, 3234-29	Bolt - 5/16-18x1 Serr Hex	1	
78	R104-1830	104-1830	Bolt - J	2	
79	R3296-2	32127-10, 3296-2, 9157404	Nut - #10 Lock	2	
80	R105-5719	105-5719	Cover - Rear Brush	1	

All original equipment manufacturers names and part numbers are used for identification purposes only, and we are in no way implying that our products are original equipment parts. Prices subject to change without notice.



Replaces Toro Greensmaster TriFlex 3320 Parts

*DPA Cutting Unit - Models 04651, 04653 & 04655
Rear Roller Brush*



Item No	R&R Part No.	OEM Part No.	Description	Qty Req	Order Quantity
81	R104-1834	104-1820, 104-1834	Idler Bearing - Assy	1	
82	R106-6917	106-6917	Pulley - Driven	1	

All original equipment manufacturers names and part numbers are used for identification purposes only, and we are in no way implying that our products are original equipment parts. Prices subject to change without notice.